




Travis Air Force Base

Environmental Restoration Program



Site SS035

September 2020



Site Name: Facilities 818 and 819

Site Description: Facilities 818 and 819 were constructed in 1970 and 1974, respectively, and are currently in use. Facility 818 is used to repair, wash, and paint aircraft. Facility 819 contains a hydraulics shop, an electro-environmental shop, a wheel and tire shop, and a hazardous accumulation area.

Trichloroethene and total petroleum hydrocarbons as diesel were identified as groundwater chemicals of concern. Monitored natural attenuation was the interim groundwater remedy. Between 1997 and 2014, the TCE and TPH-D attenuated to concentrations below cleanup levels.

Selected Remedy: The Travis AFB Groundwater ROD (CH2M HILL, 2014) specified that groundwater closure monitoring should be started for this site. The Site SS035 Site Closure Report documented the closure of this site.