



Travis Air Force Base Environmental Restoration Program



Site SD034

September 2020



Site Name: Facility 811

Site Description: SD034 is located in the western part of the NEWIOU and consists of an aircraft wash rack facility with an oil/water separator (OWS) and an overflow pond. Leaks from the OWS resulted in a layer of Stoddard Solvent, containing dissolved solvents, floating on the groundwater table. The leaking OWS was replaced in 1994. The use of Stoddard Solvent to wash aircraft in Facility 811 was discontinued in September 2014.

The list of chlorinated COCs for SD034 groundwater includes trichloroethene (TCE), vinyl chloride, 1,1-dichloroethene (DCE), benzene, cis-1,2-DCE, and perchloroethene (PCE).

Selected Remedy: The Travis AFB Groundwater ROD (CH2M HILL, 2014) selected Alternative 7 (Passive Skimming and EA) to address the residual solvent contamination.