



Travis Air Force Base Environmental Restoration Program



Site SD036

September 2020



Site Name: Facilities 872/873/876

Site Description: SD036 is located in the western part of the NEWIOU and consists of a number of multiple-use shops, including a wash rack and OWS.

The list of chlorinated COCs for SD036 groundwater includes vinyl chloride, trichloroethene (TCE), 1,1-dichloroethene (DCE), cis-1,2- DCE, 1,2-dichloroethane (DCA), benzene, bromodichloromethane, and perchloroethene (PCE).

Selected Remedy: The Travis AFB Groundwater ROD (CH2M HILL, 2014) selected Alternative 5 (Emulsified Vegetable Oil and Enhanced Attenuation) to address the residual dissolved solvent contamination.