



Travis Air Force Base Environmental Restoration Program



Site SS029

September 2020



Site Name: Monitoring Well (MW) 329 Area

Site Description: SS029 is located in the southern portion of the NEWIOU. Site SS029 is an open field south of Taxiway R and includes an ordnance disposal range. Union Creek traverses the middle of the site and flows from northeast to southwest.

Groundwater contamination at Site SS029 has been defined primarily as a trichloroethene (TCE) and cis-1,2-dichloroethene (DCE) plume that lies within the boundaries of Travis AFB. The origin of the solvent contamination in the Site SS029 groundwater is unknown.

Selected Remedy: The Travis AFB Groundwater ROD (CH2M HILL, 2014) selected Alternative 3 (Groundwater Extraction and Treatment) to address the solvent contamination.